

FIG. 1




FIG. 2




FIG. 3




FIG. 4

	FRONT SIDE OF IMAGE	CENTER OF IMAGE	BACK SIDE OF IMAGE
NON-CONDUCTIVE BRUSH	1.05	1.03	1.55
CONDUCTIVE BRUSH	0.47	0.79	0.61

(CONTAMINATION ID ON CHARGING ROLLER)
(AFTER PASSAGE OF 45000 PAPERS)